

Office of the Montgomery County Engineer

Increased Rainfall Problems

- Long-standing problems have worsened
- New problem areas have developed

Types of Problems

- Stream erosion
- Problems caused by downstream owners
- Poor design or no design
- Problems where urban meets agriculture
- We anticipate problems due to poorly-maintained detention/retention basins
- Most problems are private issues

Holes Creek

■ IMG_0904.MOV

Boulder Ave

■ IMG_3508.MOV

Manning Rd Before



Manning Rd After



Lower Miamisburg Rd



Oxford Rd



Olive Rd



Shiloh Springs Rd



Needmore Rd





Needmore Rd Contd



Yankee St




Pinewood PI



Sweet Potato Ridge Rd





Questions?